





Fig. 3



1 CTS Output 2 PwrDn Input 3 RX Output 4 TX Input 5 NC - 6 *Reset Input 7-9 NC - 10 Vcc Input 11 Gnd -	Power Down Receive Data Transmit Data Reserved Reset radio (assert low to reset) Reserved 5 VDC, +/-0.3V Signal and chassis ground
--	--










Fig. Sc




Fig. 5d

